



Underwriters Laboratories Inc.

Camas, WA (360) 817-5500
Northbrook, IL (847) 272-8800
Melville, NY (516) 271-6200
Santa Clara, CA (408) 985-2400
Research Triangle Park, NC (919) 549-1400

Certificate of Compliance

Certificate Number: 261202-MH28204
Issue Date: December 26, 2002

Issued to: FIRST POWER TECHNOLOGY CO LTD
BLK C, ROOM 1916-1918
WENJIN RD, MINGDU BLDG
SHENZHEN
GUANGDONG 518101 CHINA

Report Reference: MH28204, Vol. 1, Sec. 1

This is to Certify that representative samples of Lead-Acid Batteries, Models FP612, FP623, FP628, FP632, FP645, FP650, FP660, FP670, FP6100, FP6120, FP6140, FP1208, FP1213, FP1223, FP1226, FP1220, FP1232, FP1250, FP1245, FP1272, FP1290, FP12100S, FP12120, FP12180, FP12200, FP12240, FP12250, FP12280, LFP1233, LFP1238, LFP1240, LFP1255, LFP1260, LFP1265, LFP1278, LFP12100, LFP12120, LFP12150, LFP12200, CFP2200, CFP2300, CFP2400, CFP2500, have been investigated by Underwriters Laboratories Inc.® in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1989, Standard for Standby Batteries

Additional Information: BAZR2

Only those products bearing the UL Recognized Component Mark should be considered as being covered by UL's Classification and Follow-Up Service.

The UL Recognition Marking includes:  with File MH28204 or company name.

LOOK FOR THE UL MARKING ON THE PRODUCT

Engineer:

Project Engineer
Conformity Assessment Services
Underwriters Laboratories Inc.

Review Engineer:

Senior Associate Manager
Conformity Assessment Services
Underwriters Laboratories Inc.

*A not-for-profit organization
dedicated to public safety and
committed to quality service*